2901 Airport Drive, Torrance, California 90505

R22, R44 & R66 MAINTENANCE & INSPECTION KITS - 20 OCTOBER 2022

Kits contain overhauled/exchange components and new parts for the R22 2200-hour, R44 2200-hour, R44 Cadet 2400-hour and the R66 2000-hour airframe maintenance and inspection. Please refer to appropriate Illustrated Parts Catalog for kit contents. Specifications and prices are subject to change without prior notice.

Dealers and Service Centers may pay the core charge and/or submit exchange components to RHC in advance of kit shipment. Core charge includes a \$500.00 charge for the tail rotor assembly. RHC will inspect exchange components to determine core value. Please specify aircraft serial number when ordering.

<u>Description</u>	P/N	<u>Price</u>	Core P/N	Core Charge
*R22 Beta	KI-2202	\$106,000	R7352	\$15,300
*R22 Beta II	KI-2203	\$106,000	R7952	\$15,300
R44 Raven I/Cadet	KI-4402	\$159,000	R8211	\$39,060
R44 Raven II	KI-4403	\$164,000	R8212	\$39,060
R66 Turbine	KI-6602	\$201,000	R8481	\$41,050

^{*}Includes KI-217-1 R22 Bladder Fuel Tank Retrofit Kit; deduct \$11,600.00 if previously installed.

ENGINE BUILD-UP KITS

Includes all engine cooling panels. Note: Build-up kits are not required when purchasing an RHC overhauled/exchange engine. Use of MT562-1 (\$1,100.00 for O-360-J2A) or MT563-1 (\$1,210.00 for O-540-F1B5 & IO-540-AE1A5) scroll-to-engine drill jigs is recommended.

<u>Description</u>	<u>P/N</u>	<u>Price</u>
O-320-B2C	KI-2204	\$3,140 (no longer includes oil lines)
O-360-J2A	KI-2205	\$3,350 (specify ship S/N)
O-540-F1B5	KI-4405	\$5,730
IO-540-AE1A5	KI-4406	<mark>\$5,640</mark>

INTERIOR REPLACEMENT KITS

Includes new seats, carpet (charcoal only), insulation, cyclic and collective boots, etc. Must specify color; gray, tan or charcoal.

Description	<u>P/N</u>	<u>Price</u>
R22 Velour	KI-2206-1	\$3,500
R22 Leather	KI-2206-2	\$4,000
R44 Velour	KI-4407-1	\$8,300
R44 Leather	KI-4407-2	\$9,100
R66 Leather	KI-6603	\$15,900

Dealers and Service Centers will receive a 10% discount on all kits. Discount does not apply to core charges. Crating is included in the price. The RHC limited warranty is 1-year or 1000-hours (whichever event occurs first).

For further information or questions, please contact Robinson Customer Support (310) 539-0508.